

SERVICE NOTE

Date : May 17, 2023

Objet :

- Inspection of the frame plates making the connection with the upper beam.

Appareils concernés :

- Skypper trikes until 2021.

Inspection et action à réaliser :

The frame plates making the connection with the upper beam of the Skypper are essential parts that require special attention. A meticulous visual check must be carried out systematically before each flight.

In particularly hard conditions of use on the ground (unprepared take-off runways, strong crosswinds), repeated stresses can be generated leading to accelerated fatigue; cracks may then appear.

In this case, the flights must be imperatively suspended and you must contact the Air Création factory in order to find a solution to the problem.

