

SERVICE NOTE

Date : 04/03/2016

Purpose :

- Control of aluminium front tube fixing plates (N°E110910 & E110920) of the upper beam.

Concerned trikes :

- All the LST Skypper trikes.

Inspection and action to be realized :

- The front tube fixing plates are essential parts which require a very important attention. A visual control must be systematically realized before every flight. It was noticed that cracks could appear on the top or back part of the front tube fixing plates (see drawing). In this case the flights must be suspended and the plates must be replaced. Contact the factory in case of doubt.
- The front tube fixing plates will have to be changed systematically during the 300 hours / 3 years overhaul. A new reinforced model is available.

