

## ***SERVICE BULLETIN***

### **KAIR12005 – 5-Spoke Rim Bearing Assembly**

**LANAS le 21 November 2012**

**SUBJECT : Verification of condition of rear rim bearing assembly**

**Aircraft Concerned: Skypper and Tanarg trikes**

#### **Inspection and action items:**

- Following a problem that occurred on a trike (incorrect assembly of bearings leading to the break of the blocking screw), it is requested for all owners of concerned trikes to check the assembly of bearings in the 5-spoke rear rims. To do this you must dismount the wheel fairings, then screw back in the screw and aluminum crosspiece (the crosspiece should lightly touch the bearing). You must then turn the wheel quickly and observe if the screw and crosspiece oscillate. If that happens, then the bearing is misplaced in the hub. Flight is prohibited until you contact Air Creation in order to learn the corrective procedure to follow.

