

SERVICE NOTICE

Date : 15 Septembre 2016

Subject:

- Replacement of hanging screw M10x110.

Aircraft concerned:

- All trikes.

Inspection and actions to be taken:

- The hanging screw of the trike is a vital part which endure important stresses. Its life limit is 300 hours, as all nuts and screws of the wing. We noticed that this instruction is little applied. We must remind that it's mandatory to repalce the hanging screw every 300 hours.

